Building Safety Certificate of DAV Ispat Public School, 9E (Senior wing)

T E Civil department personnel visited <u>DAV Ispat Public School, 9E (senior wing)</u> and inspected all the structures thoroughly. <u>DAV Ispat Public School, 9E (senior wing)</u> buillidng found to be structurally stable and safe.

VG 1/10724 Rakesh Babu Helpuri राजेला जावा देलपुरी सहायक महाप्रकचक (टी. ई. सिविज सेल, बोकारो स्टील प्लान्ट